

VEHICLE INSPECTION REPORT

001588

HAMM HD10CVV

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2013	Fuel Type	Diesel	Body Style	ROLLER
Year	2013	Colour		Gearbox	Hydrostatic
Mileage	1,886 Hours Not Warranted	VIN	H1991286	Axle Combi	Tandem

COLLECT FROM PRESTON ROLL BAR, VIBRATING ROLLER, PLATE UNREADABLE, NO STAMPED VIN

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



